

## Windows Laptops/Netbook related

### **HP laptop cannot boot USB Windows 10 installation or cannot update to Windows 10 ver 1709.**

Some HP model has this issue.  
Solution: update BIOS.

Model example: HP 17-G188CA

Unique solution ID: #1039

Author: n/a

Last update: 2018-04-27 17:55