

Windows Laptops/Netbook related

HP laptop showed "Detection Verification" with ! (exclamation mark).

HP laptop Device Manager showed "Detection Verification" with ! (exclamation mark).

Solution:

1. Uninstall it.
2. Download the Realtek Driver form HP's product site and install it.
3. Installation will ask to uninstall the previous driver, then system will reboot and install the downloaded one.
4. After installation, reboot the system again and check. It should work now,

<https://h30434.www3.hp.com/t5/Notebook-Hardware-and-Upgrade-Questions/Detection-Verification-Driver-Could-Not-Load/td-p/6692791>

Unique solution ID: #1056

Author: n/a

Last update: 2019-01-24 21:20