

Windows Laptops/Netbook related

Some Asus laptop models cannot adjust brightness with FN+F keys after Windows 10 1803 installed.

Solution: Update the **Intel video driver** through Windows update over internet will solve the issue.
Model example: Asus X541UA-BS31, ROG GL552vw

No need to update nVidia VGA driver.

Unique solution ID: #1049

Author: n/a

Last update: 2018-07-05 18:29